


Kelford

KELFORD CAMS

HSV 300kw

LS camshaft upgrade

HSV 300kw LS engines are prone to destroying valve springs due to excessive valve train harmonics that spike above 5600rpm. This problem is caused by the O.E camshaft design.



Kelford have designed a replacement camshaft & valve train package that cures this problem. It also provides better performance than the factory camshaft.

PART NUMBERS REQUIRED

CM108KKF
MNVSL1DKF
VL172/4SP

DESCRIPTION

Kelford roller camshaft
Kelford Valve spring, locator, retainer & stem seal kit
Sealed Power roller lifter (pack of 4)

AUSTRALIA

1300 364 350

NEW ZEALAND

0508 364 350



precision